

# Oil Field Environmental Incident Summary

**Incident:** 20140101103718      **Date/Time of Notice:** 01/01/2014 10:26

**Responsible Party:** EOG Resources, Inc.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** WAYZETTA 148-0311H

**Field Name:** PARSHALL

**Well File #:** 26929

**Date Incident:** 12/31/2013      **Time Incident:** 13:30

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 153

**Rng:** 90

**Sec:** 3

**Qtr:** SW NW

**Location Description:**

**Submitted By:** Luigi Heydt

**Received By:**

**Contact Person:** Luigi Heydt  
600 17TH ST STE 1000N  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	220	barrels	30	barrels	220	barrels
Other	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/5/2015

**Clean Up Concluded:** 1/3/2014

**Risk Evaluation:**

**Areal Extent:**

**Potential Environmental Impacts:**

**Action Taken or Planned:**

Vac trucks were called to remove the standing fluid and the affected soil in the area will be scraped up and hauled to disposal. The rig crew had loaders onsite that they were scraping the affected area with.

**Wastes Disposal Location:** Clean Harbors

**Agencies Involved:**

**Updates**

---

**Date:** 1/2/2014      **Status:** Inspection

**Author:** Miller, Adam

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Met with Luigi Heydt at the location, and he escorted me around the premises. Entire well pad is bermed, and it is evident that spill remained on location. NDIC retains oversight.

---

**Date:** 1/2/2014      **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release due to unspecified cause, during drilling or workover activities, remained on location, according to the report. However, due to size of release, followup is necessary to confirm on-site containment in order to leave oversight in NDIC hands.

---

**Date:** 1/21/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Re-inspected site by mistake. 1/21/2014 at 4:20 on location, spill was within tank battery on SE corner of pad. No stain visible in field stubble adjacent to tank battery berm on south side, field is ice/snow covered.

---

**Date:** 4/18/2016    **Status:** Correspondence

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Bill Suess sent a No Further Action letter dated April 18, 2016.